

<b>Airworthiness Directives and Modification Statement</b>				<b>Dated:</b> 04/11/2015	<b>Date of Construction</b>			
<b>ATS 1962</b>					<b>MNTH/YEAR</b>			
<b>Aircraft Type:</b>	EXTRA EA300/L	<b>Registration:</b>	G-BZII	<b>Serial Number:</b>	119	Sep-00	<b>Total Time:</b>	566.2
<b>TCDS:</b>	EASA.A.362 Issue 07							
<b>Engine Type:</b>	LYCOMING AEIO-540-L1B5			<b>Serial Number:</b>	L-27717-48A	Aug-00	<b>Engine Hours:</b>	566.2
<b>Propeller Type:</b>	MT MTV-9-B-C/C200-15			<b>Serial Number:</b>	00-109	Jul-00	<b>Prop Hours:</b>	64.3

<b>Airframe LBA ADs to issue:</b>		04/11/2015								
AD No	Description	Applicability	Hours	Date	Complied With			Hours	Due at	
					Months	Hours	Date			Remaining
						Day	Month	Year		
1992-199	Elevator mass balance	N/A to type	N/A	N/A						
1993-081	Rudder control cable sleeve	N/A to type	N/A	N/A						
1993-145R2	Wing root rib	N/A to type	N/A	N/A						
1994-043R1	Upper longeron cut out bridge	N/A to type	N/A	N/A						
1994-258	Canopy latches	N/A to type	N/A	N/A						
1995-125	Air inlet screen	N/A to type	N/A	N/A						
1995-126	Firewall and fire protection	N/A to type	N/A	N/A						
1995-443	Rudder pedal control stop	N/A by S/N	N/A	N/A						
1997-203R2	Front seat belt cover	N/A to type	N/A	N/A						
1998-001	Tail wheel support	S/S by EASA 2009-0160	N/A	N/A						
2002-408	Fuel selector valve	PCW	N/A	N/A		22	5	2003		
2003-001R1	Upper longeron at horizontal stab	N/A to S/N	N/A	N/A						
2004-489	Bottom fuselage and firewall sealing	X-refer EASA AD D-2004-489	At lower fuselage panel refit		566.2	4	11	2015		

<b>Airframe EASA ADs to issue:</b>		22-2015								
AD No	Description	Applicability	Hours	Date	Complied With			Hours	Due at	
					Months	Hours	Date			Remaining
						Day	Month	Year		
D-2004-489	Bottom fuselage and firewall sealing	CW	At lower fuselage panel refit		566.2	4	11	2015		
2006-0281	Upper longeron at horizontal stab	N/A by S/N	N/A	N/A						
2006-0375	Carling swithces	N/A by type	N/A	N/A						
2009-0160	Tail spring support	PCW	Mod carried out, AD/SB compliance terminated		532.6	25	10	2013		





1000 Hour A/F inspection			Inspect		1000	N/A	0.0						433.8		
6000 Hour A/F life			Inspect/Replace		6000	N/A	0.0						5433.8		

**Extra Service Bulletin/Service Letter** Page 4

SB/SL No	Description	Applicability	Hours	Date	Complied With				Hours Remaining	Due at Date
					Hours	Date				
SB-300-1-01-A	Gascolator bowl wire locking	CW	50	12	566.2	4	11	2015	50.0	04/11/2016
SB-300-1-04-A	Centre tank to filler neck hose	PCW	N/A	N/A	170.6	23	9	2004		
SB-300-1-05-A	Engine fuel pump vent	PCW	N/A	N/A	256.7	18	9	2006		
SB-300-1-06	Single oil cooler	N/A Dual Cooler Fitted	N/A	N/A						
SB-300-1-11-A	Safety clamps on Garmin avionics units	CW	50	12	566.2	4	11	2015	50.0	04/11/2016
SB-301-15	Throttle control cables	CW	50	12	566.2	4	11	2015	50.0	04/11/2016
SB-300-1-91-B	MLG U-spring mounting clamp	N/A by model	N/A	N/A						
SB-300-1-92-A	Elevator mass balance	N/A by model	N/A	N/A						
SB-300-1-93-B	Rudder cable compressive sleeve	CW	N/A	N/A	532.6	25	10	2013		
SB-300-1-95-A	Seat attachment	N/A by model	N/A	N/A						
SB-300-1-96-A	Additional aileron hinge	N/A by S/N	N/A	N/A						
SB-300-1-97-B	Front seat seat belt cover installation	N/A by model	N/A	N/A						
SB-300-1-98-A	Front seat lap belt install guide	N/A by model	N/A	N/A						
SB-300-2-04-C	Inspection of MLG mounting attach	N/A by model	N/A	N/A						
SB-300-2-93-C	Wing root rib/aux spar attachment	N/A by model	N/A	N/A						
SB-300-2-94-A	Attachment of engine control cables	N/A by model	N/A	N/A						
SB-300-2-95-F	Upper longeron at horizontal stab	N/A by S/N	N/A	N/A						
SB-300-2-97-C	Tail spring support	CW	Mod carried out, SB/AD compliance terminated		532.6	25	10	2013		
SB-300-3-04	Long range tanks to standard	N/A no conversion	N/A	N/A						
SB-300-3-93-B	Upper longeron cutout bridge	N/A by model	N/A	N/A						
SB-300-3-94-A	Canopy latches	N/A by model	N/A	N/A						
SB-300-3-95-B	Rudder pedal saftey stop	N/A by S/N	N/A	N/A						
SB-300-4-04-A	Bottom fuselage sealing	X-refer EASA AD D-2004-489	At lower fuselage panel refit		566.2	4	11	2015		
SB-300-4-94-A	Pitot static drain installation	N/A by model	N/A	N/A						
SB-300-5-94-A	Air inlet screen	N/A by model	N/A	N/A						
SB-300-6-94-A	Fire protection cowling and firewall	N/A by model	N/A	N/A						
SB-300-7-94-A	Fuel selector	N/A by model	N/A	N/A						
SB-300-8-94-A	Hydraulic brakes	N/A by model	N/A	N/A						
SL-300-09-02	Fuel selector leakage	PCW	N/A	N/A		22	5	2003		

Statement prepared by: J N Parr Company: Air Training Services Ltd

Signature: Date: 04/11/2015